FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer — Arun Xavier. W
2. Name of the School — Sudarsanam Central School
3. Location with name of Education District/ Sub. District — Thiruvalla, ward-X
4. Classification of Building as specified in column 4 of the application for fitness certificate and size. — Building no 61 R.C.C Three storyed building Planned building 1 X 38.58 X 39.06 X 10 m
5. Period for which the certificate is issued — 2023 - 2024
6. Nature of defects , if any
   a) Foundation and basement — NIL
   b) Superstructure — –
   c) Doors and Windows — NIL –
   d) Wood work wrought and put up
   e) Roof
   f) Flooring
   g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner — Yes - Minor cracks in partition wall ~~missing~~ work
8. Whether maintenance works have been done properly — NIL Retrofitting work carried out for satisfaction of structural cracks found in previous year inspection
9. Whether the structure is sound or not for conducting classes — Satisfactory Yes

Note : *1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.*

Fitness is issued as per the report of structural engineers report certifying the retrofitting activities completed for rectifying structural cracks.

CERTIFICATE

certified that the school building was inspected by me on 01/07/2023 found to be fit / unfit to conduct classes, for the period 2023-2024 and reasons stated above. for the

Place : Kozhencherry

Date : 01/07/2023

Varun MANAGER
~~SUDARSAN~~AM CENTRAL SCHOOL
SCHOOL CODE:75601, Aff.No.930652
ARANMULA
(Seal)